



The Videomax I Pixel Repair System is a tool for restoration of normal operation to monitors that have developed a ghosted image, or frozen pixels during their operational life.

The system provides:

- Restoration of normal monitor function.
- The full screen resolution is addressable.

Able to improve or remove from any monitor:



- Ghosted images
- Frozen pixels
- Able to drive high resolution monitors.

Specification

Supported resolutions	All
Common resolutions	2048 x 2048 2560 x 1600
Repair tools	14 modes
Repair cycles supported	Unlimited
Host Processor	W7 or XP
Compatibility	Any monitor

The Pixel Repair system is independent of the Operating system and application software that has caused the ghosted image.

Although not all pixel problems are repairable, the Pixel Repair System is able to remove ghosted images, and restore normal pixel function in many situations.



ThruPut Limited operates a policy of continuous improvement and information in this document is subject to change without notice.

Page 1 of 1

Ref: Pixel repair system DN 1449-0000 V 2.2